

MIT OpenCourseWare
<http://ocw.mit.edu>

2.830J / 6.780J / ESD.63J Control of Manufacturing Processes (SMA 6303)
Spring 2008

For information about citing these materials or our Terms of Use, visit: <http://ocw.mit.edu/terms>.

Control of Manufacturing Processes

Subject 2.830/6.780

Spring 2008

Lecture #3


“Process Variation – Physical Causes
and Interpreting Data”

February 12, 2008

Agenda

- Process Definitions
 - Geometry Change Causality
- Taxonomy for Control
 - Classification of Change Methods
- “Mechanical” Examples
 - Turning
 - Bending
 - Molding
- Origins of Variation
 - States and Properties

Process Model for Control




$$\underline{Y} = \Phi(\underline{\alpha})$$

$\underline{\alpha} \equiv$ process *parameters*

What are the α 's?

Back to the Process: What Causes the Output Change?

- A Directed Energy Exchange with the Equipment



Modes of Geometry Change?


- **Removal** of Material
- Plastic **Deformation** of Material
- **Addition** of Material
- **Formation** of Material from a Gas or Liquid

- Any others???

What Controls the Geometry Change?

Location and Intensity of Energy Exchange


- Examples:
 - location of max. shear stress in turning



What Controls the Geometry Change?

Location and Intensity of Energy Exchange

- Examples:
 - heat transfer at the mold surface in injection molding



Control of Geometry Change?

Location and Intensity of Energy Exchange

- Examples:
 - location of laser beam in laser cutting



Control of Geometry Change?

Location and Intensity of Energy Exchange


- reaction rate - time product on substrate surface in LPCVD



Control of Geometry Change?


Location and Intensity of Energy Exchange

- displacement field in sheet forming :




Two Extremes of Interactions

Area of $E(t) \ll$ Total Area: Serial Process



Area of $E(t) \sim$ Total Area: Parallel Process



Two Extremes of Interactions

- Concentrated, “Lumped” Energy Port
 - Small Area Wrt Total Part Geometry
- Distributed Energy Port
 - Area \sim Total Part Geometry

What Determines Part Geometry Change?

- For Lumped case:
 - time - trajectory of the port location
 - e.g. tool paths
- For Distributed Case:
 - Shape of the energy distribution
 - patterns
 - molds
 - masks

Examples

- Serial (Lumped) Processes
 - Machining - Tool Path
 - Laser Cutting - Beam path
 - Bending - Tool Depth
 - Stereolithography - Beam Path
 - Three D Printing - Binder Path

Examples

- Parallel (Distributed) Processes
 - Draw Forming - Die Shapes
 - Injection Molding - Mold Shape
 - Chemical Etching - Mask Shape
 - CMP - Tool Shape
 - Plating - Substrate Shape

Toward a Process Taxonomy

- Classify by Change Mode
 - Why?
- Classify by Interaction (Sensitivity, resolution parallel)
 - So what?
- Classify by Energy Domain
 - Who cares??

Flexibility, controllability, rate

Rate, resolution

Process Taxonomy for Control


Transformation Mode	SERIAL				REMOVAL	PARALLEL			
Energy Source	Mechanical	Thermal	Chemical	Electrical	Mechanical	Thermal	Chemical	Electrical	
	Cutting Grinding Broaching Polishing Water Jet	Laser Cutting "Flame" Cutting Plasma Cutting		WIRE EDM	Die Stamping CMP		ECM Photolithography Chem Milling	EDM	

Transformation Mode	SERIAL				ADDITION/JOINING	PARALLEL			
Energy Source	Mechanical	Thermal	Chemical	Electrical	Mechanical	Thermal	Chemical	Electrical	
	Ultrasonic Welding 3D Printing	Laser Sintering		E-Beam Welding Arc Welding Resist. Welding	HIP Inertia Bonding Phys. Depos.	Sintering	LPCVD Plating		

Transformation Mode	SERIAL				FORMATION	PARALLEL			
Energy Source	Mechanical	Thermal	Chemical	Electrical	Mechanical	Thermal	Chemical	Electrical	
		Plasma Spray DBM	Stereolithography			Casting Molding	Diffusion Bonding		

Transformation Mode	SERIAL				DEFORMATION	PARALLEL			
Energy Source	Mechanical	Thermal	Chemical	Electrical	Mechanical	Thermal	Chemical	Electrical	
	Bending Forging(open) Rolling	Line Heating			Drawing Forging(die)				

Process Model for Control




$$\underline{Y} = \Phi(\underline{\alpha})$$

$\underline{\alpha} \equiv$ process *parameters*

What are the α 's?

Process Parameters

- Equipment Energy “States”
- Equipment Constitutive “Properties”
- Material Energy “States”
- Material Constitutive “Properties”



Energy States

Energy Domain

Energy or Power Variables

Mechanical

$F, v; P, Q$ or $F, d; \sigma, \varepsilon$

Electrical


V, I

Thermal

$T, ds/dt$ (or dq/dt)

Chemical


chemical potential, rate



Properties

- *Extensive*: GEOMETRY
- *Intensive*: Constitutive Properties
 - Modulus of Elasticity, damping, mass
 - Plastic Flow Properties
 - Viscosity
 - Resistance, Inductance, Capacitance
 - Chemical Reactivity
 - Heat Transfer Coefficient

A Model for Process Variations




- Recall: $\underline{Y} = \Phi(\underline{\alpha})$
- One or more α 's “qualify” as inputs : \underline{u}
$$\underline{Y} = \Phi(\underline{\alpha}, \underline{u}); \quad \underline{u} = \text{vector of inputs}$$
- The first order Variation ΔY gives the “Variation Equation”

Parallels From Lecture 2

Image removed due to copyright restrictions. Please see Fig. 26 in Boning, D. S., et al. "A General Semiconductor Process Modeling Framework." *IEEE Transactions on Semiconductor Manufacturing* 5 (November 1992): 266-280.

The Variation Equation



$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

Disturbance
Sensitivity


Disturbances

Control
Sensitivity or
"Gain"

Control Inputs

Simple Machining

- Process Type?
- Equipment States and Properties?
- Material States and Properties?




Cutting Force Model

Orthogonal Cutting


$$F_c = \text{“Strength”} \times \text{Area}$$

Strength = Ultimate Tensile Strength
(UTS)


$$\text{Area} \sim b t_o$$




Sources of Variation?




Simple Machining (Orthogonal Turning)







CNC Data



Average Values




Average Values



Machining: Conclusions

- Geometry Transformation is (In General) well behaved
 - Not highly sensitive to material property variations
 - New Surface Where Tool is Located
- Dominant Sources of Variation:
 - Tool Positioning errors - Equipment Properties and States
- Feedback control of Positions is a good idea
-> CNC control!

Brake Bending



Images removed due to copyright restrictions. Please see:

<http://www.falconfab.com/MVC-016F.JPG>


<http://www.falconfab.com/MVC-007F.JPG>

<http://edevce.fujitsu.com/fj/DATASHEET/epk/fpt-100p-m20.pdf>

Bending

- Process Type?
- Equipment States and Properties?
- Material States and Properties?

Simple Model : Pure Moment Bending




Constant Radius Tool

Simple Bending Mechanics: Parameter Effects

- Tool Shape (R_{tool}) determines the shape under load
- Elastic Springback determines the final shape
- What determines the springback?


Simple Bending Model



K = curvature of the tooling
 h = thickness of the sheet
 $\epsilon(y)$ = through thickness strain

What is $M(K)$
(or $K(M)$) ?

Simple Beam Theory



$$\varepsilon(y) = Ky$$


$$\varepsilon = Ky$$

$$M = \int_{-h/2}^{h/2} \sigma(y) y b dy$$


moment arm

dA

$$\sigma(y) = ?$$



Elastic Perfectly Plastic Model




$$M = \frac{3}{2} M_y \left(1 - \frac{1}{3} \left(\frac{K_y}{K} \right)^2 \right)$$

$$K_y = \epsilon_Y / (h / 2)$$

$$M_y = EI K_y$$

The M-K Curve



Final Shape: Springback

$$\Delta K = \frac{M_{\max}}{EI} \therefore K_{part} = K_{tool} - \Delta K$$

K = shape of tool

E = material property


$$I = \frac{1}{12}bh^3 \text{ cubic dependence on thickness}$$

$$M_{\max} = ?$$

Strong Dependence
on yield properties

$$M_{\max} = \Phi (K_Y, EI)$$

Effect of Material Variations: Increase in Yield Stress




Bending Experiments




- Bend to 2 different depths
- Two different materials
 - 0.028" Steel
 - 0.032" Aluminum

Steel vs. Aluminum



Bending by Operating Point



Other Possible Variations

- Yield Stress (+ 10% reported)
 - Chemistry, working history
- Thickness
 - Rolling mill quality
 - Design vs. manufacturing specs
- Tooling Errors

Conclusions

- Some Variations Easily Explained
 - Deterministic parameter changes
 - Thickness and Material Selection Δm_p (Material Parameter)
 - Intentional Input changes
 - Depth changes Δe_s (Equipment state)
- Other Variations ???
 - Property Variations within Material Δm_p
 - Machine Errors Δe_p and Δe_s (e.g. deflection and position error)

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

Conclusions for Brake Bending


- Equipment Errors have Strong Effect on Final Shape
 - Punch Penetration -> Δe_s (Equipment state)
 - Die Width -> Δe_p (Equipment Parameter)

SO WHAT?



Large $\partial Y / \partial \alpha$
Large $\Delta \alpha$

Injection Molding



Injection Molding Process

Process Type?

Equipment States and Properties?

Material States and Properties?





Image courtesy Wikimedia Commons, <http://commons.wikimedia.org>


Geometry Determinants

- Mold Shape
- Material Shape Change upon Cooling
 - Residual Stress Effect
 - Thermal Expansion or contraction
- Extent of Mold Filling



Key Material Properties: Flow into Mold

$$P = R(v) Q$$



Effect of Temperature on Flow

$Q = P/R$ $R = \text{resistance to flow} \propto \nu$

$$\nu(T) = Ae^{ER(T_0-T)}$$


where:

$T = \text{temperature}$


$R = \text{gas constant}$

$E = \text{activation energy for viscosity}$

Key Material Properties: Cooling



Packing Phase




Heat Transfer: Filling

- $T_{\text{part}} > T_{\text{mold}}$ therefore always cooling
- Interior hotter than surface
- If T_{part} on surface $< T_g$ flow stops
 - Short Shot
- Viscosity is strong function of Temperature

Heat Transfer in the Mold

- $q = k A \partial T / \partial x$
 - Rate decreases as $\partial T / \partial x$ decreases
 - Mold heat & polymer cools
- $dT/dt = \alpha \partial^2 T / \partial x^2$
 - $\alpha = k / \rho C_p$
 - Polymers have low k and high C_p



Process Control Issues

- Control Change in Shape upon Cooling
 - Consistent Mold Filling
 - Consistent Mold Pressure
 - Consistent Residual Stresses
 - Consistent Thermal environment
 - Consistent Thermal Distortion

Typical Equipment Control Systems

- Injection Velocity or Injection Pressure
- Nozzle Temperature
- Mold Temperature
- Barrel Heater Temperature

***Equipment
States***

Sources of Variation

- Material Properties
 - Flow Properties
 - $v(T)$ relationship (especially if moist)
 - Thermal properties (ditto)
 - Also effects of “regrind”

Example: Effect of Blending






Figure by MIT OpenCourseWare.

Lab Data


- Variable Hold Time
- Variable Injection Velocity








Injection Molding Data




Injection Molding NTU



Shift Changes

I.M. NTU (no Group 1)




Sources of Variation

- Equipment Properties
 - Heat Transfer Properties
 - Mold Flow Passages
- Equipment States
 - Barrel and Nozzle Temperatures
 - Mold Temperatures
 - Flow Rates
 - Packing Pressure

Conclusions

- I.M. is a Complex, Parallel Formation Process
- Strong Dependence on Material Properties
 - Viscosity sensitivity
 - Heat Transfer Sensitivity
- Thermal State Must be Well Controlled
 - Many opportunities on the equipment
 - Material State very hard to do
 - Distributed
 - Interference with Process

Conclusions: Variation


$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$


Disturbances

- Equipment Property Changes
- Material Property Changes
- Material State Uncertainty
- Equipment State Uncertainty

Control Inputs:
Equipment States

Process Model for Control



$$\underline{Y} = \Phi(\underline{\alpha})$$

$\underline{\alpha} \equiv$ process *parameters*

What are the α 's?

What are the Process Parameters?

- Equipment Energy “States”
- Equipment Constitutive “Properties”

- Material Energy “States”
- Material Constitutive “Properties”

Energy States

Energy Domain

Energy or Power Variables

Mechanical

$F, v; P, Q$ or $F, d; \sigma, \varepsilon$

Electrical

V, I

Thermal

$T, ds/dt$ (or dq/dt)


Chemical

chemical potential, rate

Properties

- *Extensive*: GEOMETRY
- *Intensive*: Constitutive Properties
 - Modulus of Elasticity, damping, mass
 - Plastic Flow Properties
 - Viscosity
 - Resistance, Inductance, Capacitance
 - Chemical Reactivity
 - Heat Transfer Coefficient
- Which has the highest precision?

A Model for Process Variations



- Recall:
- One or more α 's “qualify” as inputs : \underline{u}

$$\underline{Y} = \Phi(\underline{\alpha}, \underline{u}); \quad \underline{u} = \text{vector of inputs}$$

- The first order Variation ΔY gives the “Variation Equation”

The Variation Equation

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

Disturbance
Sensitivity

Control
Sensitivity or
"Gain"

Control Inputs


Disturbances

Primary Process Control Goal: Minimize ΔY

How do we make $\Delta Y \rightarrow 0$?

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

- hold u fixed ($\Delta u = 0$)
 - operator training (SOP's)
 - good steady-state machine physics
- minimize disturbances
 - $\Delta \alpha \rightarrow \Delta \alpha_{\min}$



This is the goal of Statistical Process Control (SPC)

OR

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u \quad \Delta Y \rightarrow 0$$

- hold u fixed ($\Delta u = 0$)
- minimize the term: $\frac{\partial Y}{\partial \alpha}$ the disturbance sensitivity

This is the goal of Process Optimization

• Assuming $\frac{\partial Y}{\partial \alpha} = \Phi(\underline{\alpha})$ $\underline{\alpha}$ = operating point

OR

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u \quad \Delta Y \rightarrow 0$$

- manipulate $\Delta \underline{u}$ by measuring ΔY such that

$$\Delta u \frac{\partial Y}{\partial u} = - \frac{\partial Y}{\partial \alpha} \Delta \alpha$$

This is the goal of Process Feedback Control

- Compensating for (not eliminating) disturbances

Statistical Process Control

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

Detect
and
Minimize

Process Optimization


$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

Empirically
Minimize

Output Feedback Control

$$\Delta Y = \frac{\partial Y}{\partial \alpha} \Delta \alpha + \frac{\partial Y}{\partial u} \Delta u$$

$$\frac{\partial Y}{\partial u} \Delta u = -\frac{\partial Y}{\partial \alpha} \Delta \alpha$$



Manipulate
Actively
Such that

Compensate for Disturbances

Process Control Hierarchy

- Reduce Disturbances
 - Good Housekeeping
 - Standard Operations (SOP's)
 - **Statistical Analysis and Identification of Sources (SPC)**
 - **Feedback Control of Machines**
- Reduce Sensitivity (increase “Robustness”)
 - **Measure Sensitivities via Designed Experiments**
 - Adjust “free” parameters to minimize
- Measure output and manipulate inputs
 - **Feedback control of Output(s)**